



## Video microscope for fiberoptic connector inspection

The eye-safe CI-1100 Connector Inspector is a portable video microscope used to inspect fiber optic connector endfaces for contamination. The handheld probe design makes it easy for users to inspect both patchcords and hard-to-reach in-adapter connectors.

The CI-1100-A2 package includes a folding LCD monitor, 4 inspection tips, a charger/adapter, and a carrying case. An optional USB adapter is also available for the capture of images on a PC.

Lightel offers a large variety of adapter tips, allowing you to view almost any connector in any location.











## **Features**

- Optional USB add-on for image capture or Pass/Fail analysis on a PC
- 3.5" fold-up monitor provides easy viewing in a compact package
- Quick and easy focus
- Ideal for inspecting both patchcords and adapter bulkhead connectors

## **⇒** Specifications

Probe		
Magnification	400X (w/9" monitor)	
Field of View	~425µm x 320µm (standard) ~640µm x 480µm (lower magnification option)	
Resolution	0.5µm detectable	
Focus	Manual adjustment, 2mm max travel	
Light Source	Blue LED	
Dimensions	35mm diameter x 175mm length (without tip)	
Weight	200g	
Monitor		
Display	3.5" TFT-LCD, 960 x 240px Adjustable brightness and contrast	
Dimensions	105mm x 90mm x 45mm (folded)	
Weight	255g (without battery)	
Power Supply	9.6V battery pack or AC power supply	
Battery Life	4 hours	
Charger/AC Adapter	US, EU, UK, and Australian versions available	
Operating Temperature	0°C to 50°C	
Storage Temperature	-20°C to 70°C	

CI-1100-A2 Package	
1 Probe (CI-1100)	
1 LCD monitor	
Rechargeable battery pack (inside LCD monitor)	
1 AC power adapter/battery charger	
1 Universal 2.5mm tip for PC type male connectors	
1 Universal 1.25mm tip for PC type male connectors	
1 Tip for SC/PC and FC/PC type female connectors	
1 Tip for LC/PC type female connectors	
1 Tip box	
1 Carrying case	

Key Options	
USB2.0 Adapter	Use the CI-1100 probe to view, capture, and store images on a Windows® PC
ConnectorView Plus Software	Pass/Fail analytical and reporting software for a Windows® PC
"Hot" Fiber Filter	Inspect live fiber connectors. Useable to at least 20dBm. (higher power would not damage the unit, but may not provide useful images)
Tip Adapter	Use and CI-1100 tip with the CI-1100

